



Destiny Outage

This past week we had an unfortunate outage with the Destiny Library Management system. The disruption of service was due to an HPE DL360 Gen 8 server detecting a single fan failure as a critical event. This detection signaled a redundant fan insufficiency that caused the server to shut down and prevent subsequent startups during the thermal calibration check.

Lance Melancon worked with HPE support to replace the fan and bring the Destiny Management system back online. The replacement of hardware took longer than anticipated; future moves to a more robust technology will minimize these risks.

